



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA242



Photo 1 – View of Airplane from Right Wing (Photo Courtesy of FAA)



Photo 2 – View of Airplane from Rear (Photo Courtesy of FAA)



Photo 3 – View of Airplane from Left Wing (Photo Courtesy of FAA)



Photo 4 – View of Airplane from Front (Photo Courtesy of FAA)



Photo 5 – View of Airframe Tubing Bent from Wire Strike (Photo Courtesy of FAA)