



Photo 1 – Main Wreckage During Recovery (Photo Courtesy of FAA)



Photo 2 – Lower Fuselage Looking Forward (Photo Courtesy of FAA)



Photo 3 – Lower Fuselage Looking Aft (Photo Courtesy of FAA)



Photo 4 – Landing Gear Test (Photo Courtesy of FAA)