

ERA22LA254

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left side of empennage showing hull damage (Courtesy of FAA)



Photograph 2 - Aft of airplane at wreckage site (Courtesy of FAA)



Photograph 3 - Left front side of airplane resting against a tree (Courtesy of FAA)