



Photo 1 – View of Helicopter after Landing (Operator)



Photo 2 – View of Helicopter after Crew Egress (Operator)



Photo 3 – View of Fractured Yoke Lug (Operator)




Photo 4 – View of Fractured Flex Plate Coupling (Operator)