

NTSB ERA22LA263

N29501, Cessna 172

Photo Array



Photo 1: Overview of the airplane at the accident (Photo Courtesy of FAA)



Photo 2: Overview of the airplane at the accident (Photo Courtesy of FAA)



Photo 3: Overview of the nose, cowling section, and tree damage at the accident site (Photo Courtesy of FAA)