



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA264



Photo 1 – View of Airplane from Rear (Photo Courtesy of FAA)



Photo 2 – View of Airplane from Left (Photo Courtesy of FAA)



Photo 3 – View of Left Wing Damage (Photo Courtesy of FAA)



Photo 4 – Close-Up View of Wing Damage (Photo Courtesy of FAA)



Photo 5 – View of Dry Fuel Measuring Stick Showing No Fuel (Photo Courtesy of FAA)



Photo 6 – View of Dry Fuel Measuring Stick Showing No Fuel (Photo Courtesy of FAA)