



Photo 1 – Digital Photograph From Owner. Front View of Top of Airplane at the Accident Site. Note the Substantial Damage to the Right Wing.



Photo 2 - Digital Photograph From Owner. Right Side View of The Airplane at the Accident Site. Note the Substantial Damage to the Right Wing.



Photo 3 – FAA Digital Photograph. Right Forward Quartering View of the Airplane Following Recovery. Note the Damage to 1 Propeller Blade and Slight Damage to the Other Propeller Blade.



Photo 4 - FAA Digital Photograph. Left Forward Quartering View of the Airplane Following Recovery. Note the Separated Single Carburetor.



Photo 5 - AA Digital Photograph. View Of the Right Wing. Note the Substantial Damage.