

Airframe
N432CD
Cirrus SR22
Hobbs: 2389.8
Work order: 22063

06/14/2022
Serial Number: 0941

Performed annual inspection as per Cirrus Annual Inspection Checklist and FAR 43.15(c)(1)(2). Researched all AD's till 3rd quarter 2022. Serviced induction filter. Performed ELT check as per FAR 91.207(d). Ops check good. Battery exp. January 2023. Performed lubrication of aircraft via the lubrication chart. Serviced gascolator. Tightened rotary ignition switch. Repaired cracks in MLG wheel fairings. Removed nose fork assembly. Cleaned bearing surface and lubricated per Cirrus manual. Adjusted tension to allow nose wheel to rotate with constant 23lbs of force. Removed and replaced R/mg tire. P/N off 025-501-1, s/n off 83082147. P/N on 025-501-1, S/N on 82542106. Removed and replaced bolt for A/C compressor mount. Removed and replaced A/C compressor belt. Dressed prop as needed. Adjusted exhaust tail pipe away from belly of aircraft to prevent burn spots. Removed and replaced rh and lh brake linings. Bled brake system. Operational check good. No further defects noted. All work performed IAW Cirrus AMM and AC 43.13-1B.

I certify this aircraft has been inspected IAW an annual inspection and determined to be in an airworthiness condition at this time.

Detail of this install and inspection are on file under work order Number: 22063 at our locations as follows:
Aeropros

Gulf Shores, AL 36542
Terran Bagby
FAA Certified Repair Station Number

Engine
N432CD
Continental IO-550-N
Hobbs: 2389.8
Work Order Number: 22063

06/14/2022
Serial Number: 917207

Performed annual inspection as per Cirrus Annual Inspection Checklist. Performed oil change. Drained engine oil, removed oil filter, cut open and inspected for metal contamination none noted, installed new CH48108-1 oil filter, serviced engine oil with 8 QTS of Phillips Victory 20-w50. Removed, cleaned, gapped, and reinstalled all spark plugs. Performed Compression check and they are as follows, 1)79/80, 3)75/80, 5)73/80, 2)73/80, 4)77/80, 6)74/80. Serviced induction filter. Checked mag timing to each other and to the engine. Researched all AD's up to 2022. All work performed IAW Cirrus SR22 Service Manual and Continental EM. Ran engine and accomplished normal pressures and temps. Leak and Operational check good.

I certify this engine has been inspected IAW an annual inspection and determined to be in an airworthiness condition at this time.

Detail of this install and inspection are on file under work order Number: 22063 at our locations as follows:
Aeropros

Gulf Shores, AL 36542
Terran Bagby
FAA Certified Repair Station Number

Propeller
N432CD
Hartzell PHC-J3YF-1RF
Hobbs: 2389.8
Work Order Number: 22063

06/14/2022
Serial Number: FP282B

Performed annual inspection as per Cirrus Annual Inspection Checklist. Inspected mounting hardware and anti-ice equipment. No defects noted. Researched AD's up to 2022. Serviced with appropriate grease. Ran engine to normal pressures and temps, no leaks noted. Propeller operates as described. All work performed IAW Cirrus SR22 MM and Hartzell MM.

I certify this propeller has been inspected IAW an annual inspection and determined to be in an airworthiness condition at this time.

Detail of this install and inspection are on file under work order Number: 22063 at our locations as follows:

Aeropros

3190 Airport drive

Hangar #2

Gulf Shores, AL 36542

Terran Bagby

FAA Certified Repair Station Number