

ERA22LA275

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Left Side View (Courtesy of GSAA)



Photograph 2 - Right Side View (Courtesy of GSAA)



Photograph 3 - Interior View (Courtesy of GSAA)



Photograph 4 - Left Wing



Photograph 5 - Right Wing



Photograph 6 - Right Main Landing Gear



Photograph 7 - Pilot Side Rudder Pedals and Brake Lines



Photograph 8 - Brake Fluid Reservoir



Photograph 9 - Left Disc




Photograph 10 - Left Caliper



Photograph 11 - Right Disc




Photograph 12 - Right Caliper



Photograph 13 - Exemplar Disc Sections



Photograph 14 - Aluminum Shim



Photograph 15 - Comparison of Exemplar Phenolic Shim to Aluminum Shim

END