



Photo 1 – FAA Digital Photograph. Right Side View of the Airplane at the Accident Site.



Photo 2 - FAA Digital Photograph. Left Side View of the Airplane at the Accident Site.



Photo 3 - FAA Digital Photograph. Left Forward Quartering View of the Airplane at the Accident Site.




Photo 4 – FAA Digital Photograph. View of the Loose Hose at the Outlet of the Gascolator.




Photo 5 – Digital Photograph From Airport Manager. Right Side View of the Aft Portion of the Engine and Engine Firewall Following Recovery.