



Memorandum for Record

Heidi Kemner
Senior Air Safety Investigator
Eastern Region Aviation

June 30, 2022

Subject: ERA22LA290
Who: FAA Inspector – Hazen Rowe

In a telephone conversation, Inspector Rowe stated the following:

- He searched about 20-50 acres of land for the drone debris after he received notification of the accident and never located any debris.
- He met with the Holly Ridge Campground manager, Ms. Teresa Blackburn to search the campground and surrounding area.
- The campground was near where the pilot thought the drone strike happened.
- They used a campground vehicle to complete the search.
- They also went over the river, over the area surrounding nearby powerlines and never located any parts or pieces of a drone.
- Furthermore, Inspector Rowe asked if the local powerline company was inspecting powerlines on the day of the accident with a drone. The powerline company, Duke Energy, responded to him and stated that they were not inspecting the powerlines that day.