



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA298



Photo 1 – View of Airplane from Bottom (Photo Courtesy of FAA)



Photo 2 – View of Airplane from Top (Photo Courtesy of FAA)



Photo 3 – View of Airplane at Examination (Photo Courtesy of FAA)



Photo 4 – View of Left Fuel Tank Leak Check (Photo Courtesy of FAA)



Photo 5 – View of Right Fuel Tank (Photo Courtesy of FAA)




Photo 6 – Fuel Selector Valve after Examination (Photo Courtesy of FAA)