



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA308



Photo 1 – View of left side of the airplane (Photo Courtesy of FAA)



Photo 2 –View of cylinder No. 4 exhaust valve.



Photo 3 – View of the interior of cylinder No. 4, the exhaust valve on the right and remained in the closed position.



Photo 4 –View of the exhaust manifold and muffler.