



MEMORANDUM FOR RECORD

Investigative Photographs
ERA22LA313

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

Photographs provided by the Ronald Awad.



Photograph 1 – Accident Site.



Photograph 2 – Foreign material found in fuel filter.



Photograph 3 – Fuel sending unit.



Photograph 4 – Foreign material found in fuel tank.