



Photo 1 – View of airplane wreckage on embankment



Photo 2 – View of removed access panel



Photo 3 – View of leaking brake line