



Photo 1 – View of right wing. (Courtesy of FAA)



Photo 2 – View of wire in right wing (Courtesy of FAA)



Photo 3 – View of sliced leading edge. (Courtesy of FAA)