



NATIONAL TRANSPORTATION SAFETY BOARD
Office of Aviation Safety

INVESTIGATIVE PHOTOGRAPHS

A. ACCIDENT ERA22LA326

Location: Waynesville, OH
Date: 7/10/2022
Aircraft: Schweizer SGS-2-33A
Registration: N3616Q

NTSB IIC: Peter Wentz

Photographs provided by the Federal Aviation Administration.



Photograph 1 – Accident site – N3616Q.



Photograph 2 – Accident airplane, right front view.



Photograph 3 – Accident airplane, cockpit view.



Photograph 4 – Accident airplane, right wing tip damage.



Photograph 5 – Accident airplane, fuselage damage.