



Photo 1 – Main Wreckage (Photo Courtesy of FAA)




Photo 2 – Forward Right Fuselage And Right Wing Strut Damage (Photo Courtesy of FAA)



Photo 3 – Fuel Recovered From Gascolator (Photo Courtesy of FAA)



Photo 4 – Residual Fuel in Fuel Tank (Borescope Photo Courtesy of FAA)



Photo 5 – Empty Section of Fuel Tank (Borecope Photo Courtesy of FAA)



Photo 6 – Empty Section of Fuel Tank – Opposite View (Borescope Photo Courtesy of FAA)