



Photo 1 – Digital Photograph From Atlanta Air Salvage. Rear View of the Airplane at the Accident Site.



Photo 2 - Digital Photograph From Atlanta Air Salvage. Rear View of Portion of Left Wing Showing Structural Damage.



Photo 3 - Digital Photograph From Atlanta Air Salvage. Forward View of Portion of Left Wing Showing Structural Damage to the Main Spar.



Photo 4 - Digital Photograph From Atlanta Air Salvage. Left Side View Showing Structural Displacement of the Left Wing.



Photo 5 - Digital Photograph From Atlanta Air Salvage. Forward View of the Inboard Portion of the Right Wing Showing Structural Damage to 1 Wing Lift Strut.