



**Photo 1 – Main Wreckage – Courtesy of FAA**



**Photo 2 – Bottom View of Main Wreckage – Courtesy of FAA**



**Photo 3 – Aft View of Main Wreckage – Courtesy of FAA**



**Photo 4 – Tail Rotor – Courtesy of FAA**



**Photo 5 – Tip of Tail Rotor Blade – Courtesy of FAA**



**Photo 6 – Cable Wrap Marks on Output Shaft for Tail Rotor – Courtesy of FAA**



**Photo 7 – Lower Vertical Stabilizer – Courtesy of FAA**



**Photo 8 – Cable Penetration on Lower Vertical Stabilizer – Courtesy of FAA**



**Photo 9 – Left Horizontal Stabilizer – Courtesy of FAA**



**Photo 10 – Leading Edge of Tail Rotor Blade – Courtesy of FAA**



**Photo 11 – Cockpit – Courtesy of FAA**