



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA349



Photo 1 – View of left side of the airplane. (Photo Courtesy of FAA)



Photo 2 – View of airplane from the nose, including damage to left wing. (Photo Courtesy of FAA)



Photo 3 – View of airplane from right. (Photo Courtesy of FAA)