



**NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Eastern Region

**Photo Array**

**ERA22LA352**



**Photo 1 – View of Airplane from Right Rear at Accident Site (Courtesy of FAA)**



**Photo 2 – Front View of Airplane (Courtesy of FAA)**



**Photo 3 – View of Airplane’s Right Side – Note Damage to Control Surface (Courtesy of FAA)**