

**NTSB ERA22LA355**

N9325H, Aeronca 7BCM

Photo Array



Photo 1: Overview of the airplane at the accident site (Photo Courtesy of FAA)



Photo 2: Overview of the damage to the airplane's aft fuselage structure (Photo Courtesy of FAA)



Photo 3: Overview of the damage to the airplane's right wing (Photo Courtesy of FAA)



Photo 4: Overview of the damage to the airplane's right wing (Photo Courtesy of FAA)