



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA369



Photo 1 – View of Airplane from Left Side (Photo Courtesy of FAA)



Photo 2 – View of Airplane from Bottom (Photo Courtesy of FAA)



Photo 3 – View of Airplane from Left Wing (Photo Courtesy of FAA)



Photo 4 – View of Tachometer (Photo Courtesy of Textron)




Photo 5 – View of Magneto (Photo Courtesy of Lycoming Engines)




Photo 6 – View of Magneto with Cover Removed (Photo Courtesy of Lycoming Engines)