



Photo 1 – Front view of damaged left side cockpit (FAA photo)



Photo 2 – Top view of damaged left wing (FAA Photo)



Photo 3 – View right side of damaged fuselage (FAA Photo)