

NTSB ERA22LA385

N9968F, Cessna 172R

Photo Array



Photo 1: Overview of the airplane cockpit (Photo Courtesy of FAA)




Photo 2: Wrinkling of the floorboard in the cockpit left side of pedestal (Photo Courtesy of FAA)




Photo 3: Wrinkling of the floorboard in the cockpit right side of pedestal (Photo Courtesy of FAA)



Photos 7, 8, 9: Overview of damage to the firewall (Photo Courtesy of FAA)