



Photo 1 – aircraft accident site (courtesy of FAA)



Photo 2 - aircraft – rear view (courtesy of FAA)



Photo 3 – aircraft cockpit (courtesy of FAA)



Photo 4 – damage to left wing (courtesy of FAA)