



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA392



Photo 1 – View of Airplane’s Ground Path to Accident Site (Courtesy of FAA)



Photo 2 – Front View of Airplane (Courtesy of FAA)



Photo 3 – View of Airplane's Instrument Panel and Controls (Courtesy of FAA)