



Photo 1 – Main Wreckage (Photo Courtesy of OHSP)



Photo 2 – Right Wing Damage (Photo Courtesy of FAA)



Photo 3 – Left Wing Damage (Photo Courtesy of FAA)



Photo 4 – Propeller (Photo Courtesy of FAA)




Photo 5 – Carburetor (Photo Courtesy of FAA)



Photo 6 – Air Filter (Photo Courtesy of FAA)