


ERA22LA410

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane where it came to rest. (Courtesy of operator)



Photograph 2 - View of damage to No. 1 cylinder.