



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA413



Photo 1 – Front view of airplane. (Photo Courtesy of FAA)



Photo 2 – View of the airplane from left rear (Photo Courtesy of FAA)



Photo 3 – View of Airplane from Left Wing (Photo Courtesy of FAA)



Photo 4 – View of the cockpit (Photo Courtesy of FAA)



Photo 5 – View of the oil filter. (Photo Courtesy of FAA)




Photo 6 – View of fuel sample collect during engine examination. (Photo courtesy of the FAA)