



Photo 1 – Digital Photograph Provided by Alachua County Sheriff's Office. Aerial View of the Airplane at the Accident Site.



Photo 2 - Digital Photograph Provided by Alachua County Sheriff's Office. Near Forward View of the Inverted Airplane At the Accident Site.



Photo 3 - Digital Photograph Provided by Alachua County Sheriff's Office. Left Forward Quartering View of the Inverted Airplane At the Accident Site. Note the Structural Damage (Buckling) of the Lower Fuselage near the Left Main Landing Gear Attach Point.