


ERA23FA023

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of aircraft wreckage on side of residential home



Photograph 2 - View of aircraft wreckage on house rooftop (Courtesy of FAA)



Photograph 3 - View of aircraft engine (Courtesy of FAA)



Photograph 4 - View of horizontal and vertical stabilizers (Courtesy of FAA)