



Photo 1 – Initial Impact Point with Trees



Photo 2 – Wreckage Path Looking West



Photo 3 – Wreckage Located Forward of Main Impact Area (Textron)



Photo 4 – One of Many Pieces of Angular Cut Wood at Accident Site



Photo 5 – Left Engine



Photo 6 – Left Propeller Assembly




Photo 7 – Right Engine



Photo 8 – Right Propeller Assembly