

ERA23FA077

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of right side of airplane showing overall damage to airplane. (NTSB Photo)



Photograph 2 - left side view of crashed airplane (NTSB Photo)



Photograph 3 - Aft view of airplane showing empennage. (NTSB Photo)