


ERA23FA078

INVESTIGATION PHOTOGRAPHS



Photograph 1 - UAV Drone photograph of initial impact site and wreckage. (Courtesy of Beverly, MA Police)



Photograph 2 - UAV Drone photograph of direct overhead view of accident site. (Courtesy of Beverly, MA Police)



Photograph 3 - UAV Drone photograph of main wreckage. (Courtesy of Beverly, MA Police)



Photograph 4 - UAV Drone photograph of left side of fuselage. (Courtesy of Beverly, MA Police)



Photograph 5 - UAV Drone photograph of cockpit damage. (Courtesy of Beverly, MA Police)



Photograph 6 - View of rotor assembly during examination. (NTSB)



Photograph 7 - View of fuselage right side during examination. (NTSB)