



Photo 1 – Front View of Main Wreckage



Photo 2 – Aft View of Main Wreckage



Photo 3 - Engine



Photo 4 – Right Magneto Hold Down Nuts