

ERA23FA136

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of airplane wreckage in tree (Courtesy of FAA)**



**Photograph 2 - Aft view of airplane in tree (Courtesy of FAA)**



**Photograph 3 - View of airplane recovered left side of wreckage (Courtesy of FAA)**



**Photograph 4 - View of airplane recovered right side of wreckage (Courtesy of FAA)**



**Photograph 5 - Front view of airplane (Courtesy of FAA)**



**Photograph 6 - View of engine (Courtesy of FAA)**