

ERA23FA163

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Yellow Gyrocopter main wreckage resting on left side



Photograph 2 - Yellow Gyrocopter main wreckage front view



Photograph 3 - Yellow Gyrocopter main wreckage bottom view



Photograph 4 - Yellow Gyrocopter main wreckage engine view

