

ERA23FA182

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (NTSB Photo)



Photograph 2 - Main Wreckage (NTSB Photo)



Photograph 3 - Main Wreckage (NTSB Photo)



Photograph 4 - Fuselage (NTSB Photo)



Photograph 5 - Top Spark Plugs (NTSB Photo)



Photograph 6 - Propeller Blade (NTSB Photo)