

ERA23FA185

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of wreckage looking aft from nose.



Photograph 2 - View of wreckage right side of fuselage.



Photograph 3 - View of wreckage looking forward from tail.




Photograph 4 - Closeup of wreckage.



Photograph 5 - View of instrument panel.



Photograph 6 - View of engine and propeller on site.



Photograph 7 - Overall view of accident site taken from initial ground impact point showing heading, lat/log and elevation.