



Photo 1 – View of Airplane as Found (FAA)



Photo 2 – Flap Handle Secure in First Notch (10 degrees) of Flaps as Found (FAA)



Photo 3 – View of Initial Ground Scar (FAA)



Photo 4 – View of Propeller after Recovery (Lycoming Engines)