



Photo 1 – Overhead Picture of Airplane Wreckage in Relation to Runway (Dorchester County Sheriff's Department)



Photo 2 – Left-Side View of Airplane at Accident Site (FAA)



Photo 3 – Front/Right View of Airplane at Accident Site (FAA)



Photo 4 – Right/Rear View of Airplane at Accident Site (FAA)



Photo 5 – Rear/Left View of Airplane at Accident Site (FAA)



Photo 6 – Cockpit (NTSB)