



Photo 1 – View of Wreckage Path from Initial Ground Scar (FAA)



Photo 2 – Main Wreckage as Found (FAA)



Photo 3 – View of Main Wreckage after Separation from Utility Truck (FAA)