

ERA23FA254

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Overall view of wreckage (NTSB)



Photograph 2 - View of wreckage with engine in background. (NTSB)



Photograph 3 - View of wreckage with location and elevation. (NTSB)



Photograph 4 -Handwritten notes on fuselage about flight control settings. (NTSB)



Photograph 5 - View of engine as discovered at end of wreckage path. (NTSB)



Photograph 6 - View of flight control cables and turnbuckles. (NTSB)



Photograph 7 - View of front of engine and propeller damage. (NTSB)