

ERA23FA256

INVESTIGATION PHOTOGRAPHS



Photo 1: View of the accident site.



Photo 2: View of an engine at the accident site.



Photo 3: Additional view of the accident site.



Photo 4: Additional view of the accident site.