

ERA23FA274

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of Piper Aircraft)



Photograph 2 - Aft Fuselage



Photograph 3 - Left Wing




Photograph 4 - Left Engine Nacelle



Photograph 5 - Cabin



Photograph 6 - Empennage



Photograph 7 - Instrument Panel




Photograph 8 - Right Wing



Photograph 9 - Right Propeller



Photograph 10 - Left Propeller



Photograph 11 - Throttle Quadrant




Photograph 12 - Fuel Selectors



Photograph 13 - RPM Indicator




Photograph 14 - Exhaust Gas Temperature Indicator



Photograph 15 - Before Takeoff Checklist (As Found)



Photograph 16 - Right Engine



Photograph 17 - Right Engine Fuel Servo



Photograph 18 - Right Engine Fuel Manifold




Photograph 19 - Left Engine



Photograph 20 - Left Engine Fuel Servo Diaphragm



Photograph 21 - Left Engine Fuel Manifold



Photograph 22 - Preflight Checklist