

ERA23FA280

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of fire damaged airplane.



Photograph 2 - View of cockpit and instrument panel.



Photograph 3 - View of fire damaged fuselage.



Photograph 4 - View of engine at wreckage site.



Photograph 5 - View of damaged three-bladed propeller.