

ERA23FA323

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wide angle view of entire wreckage.



Photograph 2 - View of engine compartment and propeller.



Photograph 3 - View of cockpit and instrument panel.




Photograph 4 - Aft view looking forward.



Photograph 5 - Closeup view of propellers.



Photograph 6 - View of engine and propellers during exam.



Photograph 7 - View of seat tracks during examination. (Courtesy of Textron)