

ERA23FA380

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fuselage and right wing



Photograph 2 - Cockpit control panel and yokes



Photograph 3 - Fuselage and propeller as viewed from front



Photograph 4 - Seatbelt attachment point where torn from fuselage



Photograph 5 - Left wing



Photograph 6 - Empennage